



FLOW DIAGRAM FOR MANUFACTURE OF CHARCOAL FROM HARDWOODS

2/8

SECTIONAL ELEVATION OF ACI CHARCOAL ACTIVATION FURNACE

FIG. 2












FIG. 4



SECTION THRU BOTTOM OF FURNACE







SECTION THRU

FIG. 8